DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-018519

Address: 333 Burma Road **Date Inspected:** 07-Dec-2010

City: Oakland, CA 94607

OSM Arrival Time: 630 **Project Name:** SAS Superstructure **OSM Departure Time:** 1500 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: See Below **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No **Delayed / Cancelled:** Yes No N/A

34-0006 **Bridge No: Component:** Orthotropic Box Girders

Summary of Items Observed:

At the start of the shift the Quality Assurance Inspector (QAI) traveled to the project site and observed the following work performed by American Bridge/Fluor Enterprises (AB/F) personnel at the locations noted below:

- A). Deck Access Hole-Insert Plate
- B). Field Splice W7/W8
- C). Field Splice W6/W7
- D). Pipe Supports
- E). QC Inspection Request

A). Deck Access Hole-Insert Plate

The QAI observed the field fit-up and tack welding Shielded Metal Arc Welding (SMAW) of the Deck Access Hole-Insert Plate (DAH-IP)identified as Weld Number (WN): 3W-PP23.5-W2-NE located on the "A" deck of the Orthotropic Box Girder (OBG) W4. The welder Ken Chappell ID-3833 performed the tack welding utilizing the Welding Procedure Specification (WPS) ABF-WPS-D15-1010, Rev. 0. The WPS was also utilized by the QC inspector Fred Von Hoff as a reference to monitor the welding and verify the welding parameters which was recorded as 140 amps by the QC inspector. The 3.2 mm low hydrogen electrode, E7018 H4R, was utilized with the welding performed in the flat (1G) position with the work placed in an approximately horizontal plane and the weld metal deposited from the upper side. The groove joint appeared to comply with the AWS joint designation identified as B-U4a and the minimum preheat temperature of 20 degrees Celsius and the maximum interpass temperature of 230 degrees Celsius were verified by the QC inspector. The work performed appeared to comply

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

with the contract documents and no issues regarding the dimensions of the root opening or planar alignment at the time of the QC inspection.

The QAI also observed the field fit-up and tack welding Shielded Metal Arc Welding (SMAW) of the Deck Access Hole-Insert Plate (DAH-IP)identified as Weld Number (WN): 6W-PP46.5-W2-S located on the "A" deck of the Orthotropic Box Girder (OBG) W4. The welder Jorge Lopez ID-6149 performed the tack welding utilizing the Welding Procedure Specification (WPS) ABF-WPS-D15-1010, Rev. 0. The WPS was also utilized by the QC inspector William Sherwood as a reference to monitor the welding and verify the welding parameters which was recorded as 140 amps by the QC inspector. The 3.2 mm low hydrogen electrode, E7018 H4R, was utilized with the tack welding performed in the flat (1G) position with the work placed in an approximately horizontal plane and the weld metal deposited from the upper side. The groove joint appeared to comply with the AWS joint designation identified as B-U4a and the minimum preheat temperature of 20 degrees Celsius and the maximum interpass temperature of 230 degrees Celsius were verified by the QC inspector. The work performed appeared to comply with the contract documents and no issues regarding the dimensions of the root opening or planar alignment at the time of the QC inspection.

At the conclusion of the tack welding the welder commence the Complete Joint Penetration (CJP) welding of the weld joint. Later in the shift the QAI, at random intervals, observed the welding and the QC inspector monitor the welding and verify the welding parameters utilizing the WPS as mentioned in the previous paragraph. The welding was not completed during this shift.

B). Field Splice W7/W8

The QAI also observed the Flux Cored Arc Welding (FCAW-G) of the weld joint identified as Weld Number (WN) W7-W8-C2. The Complete Joint Penetration (CJP) welding was performed by welding personnel Song Tao Huang, ID-3794 utilizing the WPS ABF-D15-3042B-1, Rev. 0. The WPS was also used by the QC inspector William Sherwood as a reference to monitor the welding and to verify the DC welding parameters which were noted and recorded by the QC as follows; 260 amps, 22.8 volts and a travel speed measured at 265 mm/m. The welding was performed in vertical position (3G) at approximate incline of 22 degrees with the weld progression up. The QC inspector also verified the minimum preheat temperature of 100 degrees Celsius and the maximum interpass temperature of 230 degrees Celsius. Later during the shift the QAI observed, at random intervals, the QC inspector monitoring the in process welding, the surface temperatures and verifying the welding parameters. The CJP welding was not completed during this shift.

C). Field Splice W6/W7

The QAI observed the excavation of the unacceptable discontinuities on the side plate field splice identified as WN: 6W-7W-F, repair cycle # R2. The rejectable discontinuities were discovered during the Ultrasonic Testing (UT) performed by the QC technician, Jesse Cayabyab. The discontinuities appeared to travel in the longitudinal direction of the weld axis and the excavations of the rejected areas was performed by the welder Jorge Lopez ID-6149 utilizing a high cycle grinder to remove the defects and a rotary file to bring the excavated areas into compliance with the Weld Procedure Specification (WPS) ABF-WPS-D15-1001 Repair, Rev. 0. At the conclusion of the excavations the QAI observed the QC inspector perform a visual inspection and a Magnetic Particle Test (MPT) of the excavated areas and no rejectable indications were noted. At the conclusion of the VT

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

and MPT, the welder commenced the welding of the repairs which was identified with the following Y coordinate; Y = 1000 mm.

The repair welding was performed by Mr. Lopez utilizing the Shielded Metal Arc Welding (SMAW) process as per the WPS which was also utilized by the QC inspector, William Sherwood, to monitor the welding and to verify the DC welding parameters. The QC inspector verified the DC welding parameters as 130 amps and the minimum preheat temperature of 40 degrees Celsius and the maximum interpass temperature of 230 degrees Celsius which appeared to comply with the contract documents. The welding was performed in the vertical (3G) position utilizing an E7018 H4R, 3.2 mm low hydrogen electrodes. The welding of the repair was not completed during this scheduled shift. The QAI verified the dimension of the excavation and were noted and recorded as follows; Y=1000 mm, L=90 mm, d=10 mm.

D). Pipe Supports

The QAI observed the continued fillet welding of the pipe supports identified as PS-11 located along the pier column embeds at W2-E1. The welding was performed by David Garcia ID-8789 utilizing a 3.2 mm electrode as per the Welding Procedure Specification (WPS) identified as Fillet Murex. The fillet welding was performed in vertical (3F) position utilizing a 3.2 mm electrode. The QC inspection was performed by Mike Johnson utilizing the WPS to monitor the welding and to verify the amperage.

E). QC Inspection Request

At the request of Quality Control Field Supervisor, Bonifacio Daquinag, the QAI randomly verified the visual appearance of the Complete Joint Penetration (CJP) welding of the following; the side plate field splice 6W-7W-C1,C2 and B1. The verification was performed on the "A and B" faces of the weld joint. The QAI verification was performed to verify that the welding and visual inspection performed by the QC inspector meet the requirements of the contract documents. At the conclusion of the QAI verification it appeared that the weld and the QC inspection complies with the contract documents.

QA Observation and Verification Summary

The QA inspector observed the QC activities and the welding of the field splices utilizing the WPS as noted above, which appeared to be posted at the weld station. The welding parameters and surface temperatures were verified by the QC inspector and utilizing a Fluke 337 clamp meter for the electrical welding parameters and a Fluke 63 IR Thermometer for verifying the preheat and interpass temperatures. The ESAB consumables utilized for the SMAW welding process appeared to comply with the AWS Specification and AWS Classification. The QC inspection, testing and welding performed on this shift appeared to be in general compliance with the contract documents. At random intervals, the QAI verified the QC inspection, testing, welding parameters and the surface temperatures utilizing various inspection equipment and gages which included a Fluke 337 Clamp Meter and Tempilstik Temperature indicators.

The digital photographs on page 4 of this report illustrate the work observed during this scheduled shift.

WELDING INSPECTION REPORT

(Continued Page 4 of 4)





Summary of Conversations:

There were general conversations with Quality Control Inspector Bonifacio Daquinag, Jr. at the start of the shift regarding the location of American Bridge/Fluor welding, inspection and N.D.E. testing personnel scheduled for this shift.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy 510-385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Reyes, Danny	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer